

FIG 1




FIG 2




FIG 3




FIG 4





FIG 5



men of the last of the stand hard bear the FIG 6 D D **Down Converter** i į N. S. S. M. Com. W. C. S. p р 1 1 е е X X е е **Up Converter** ŗ r 62 BPF To Microprocessor for Control Functions Reference Voltage

FIG 7